


THE ORIGINAL DOOR LOCK MONITOR SOLUTION

Designed to work with any elevator controller



BENEFITS

- Non-proprietary design permits use with any controller on the market
- Easy to install
- Meet code requirements without a full mod job
- Front DLM unit options and front/rear opening
- Technical support available
- PE-approved drawing modification services can be provided
- Satisfies NYC Building Code 2.26.5 and 3.10.12, Appendix K - required by 2020

FEATURES

- Detects jumped or faulty door circuits and prevents car movement in the event of door failure
- Separate commons for different circuits
- Universal inputs (24-250V, AC or DC)
- On-board diagnostics/troubleshooting
- Alarm relay permits audible or visual indication of presence of fault

The deadline to comply with NYC Building Code 2.26.5 and 3.10.12, Appendix K is Jan. 1, 2020.

FM1 allows you to be ready.





50 E. 153rd St. Bronx, NY 10451-2104 Ph: 718.292.9000 Fax: 718.292.2034 info@gal.com www.gal.com

REGIONAL SERVICE CENTERS

Miami – 877.241.9354 Chicago – 877.300.5830 Los Angeles – 877.300.5816 New York – 347.226.4555 Toronto – 888.425.2262