


NOTE.

CONTACTS & TERMINALS INSIDE DOTTED LINE ARE ON EXISTING A.C. CONTROLLER. BOTH SUPPLY LINES SHOULD BE OPENED AS INDICATED.



5/21/75 "BR" RELAY WITH COIL 5693 REPLACED WITH FABRICATED RELAY USING COIL S6438-23000T 39W AND RELAY RECTIFIER KBH 2506

11/15/66 ADDED OPTIONAL COOLING RESISTOR.

REVISED 4/11/66 ADDED CONDENSER

RETRACED AND ADDED CONTROL TRANSFORMER AS OPTIONAL DEVICE. (2-17-65)

REVISED 4/11/66

DATE 2-12-63

WIRING DIAGRAM FOR REPLACING A.C. BRAKE WITH HOLLISTER WHITNEY D.C. BRAKE

S-10,019